

ORIGINAL
(Red)

A P P E N D I C E S

Persons Present during January 5, 1984 Site Inspection

Virginia State Health Department

Mr. Robert Wichser
Mr. Kevin Greene
Division of Solid and Hazardous
Waste Management
101 North 14th Street
Monroe Building, Floor 11
Richmond, VA 23219

ORIGINAL
(Red)

Reynolds Metals Company

Mr. Charles Bent
Engineering Division
6601 West Broad Street
Richmond, VA 23261

Mr. Earl S. Lucas, Jr.
Plant Engineer
P. O. Box 128
Grottoes, VA 24441

Persons Contacted

Virginia State Air Pollution Control Board

Region II
Mr. Donald L. Shepherd, Director
5338 Peters Creek Road
Roanoke, VA 24019

Region V
Mr. Henry A. Moss, Director
8205 Hermitage Road
Richmond, VA 23228

Virginia State Water Control Board

Piedmont Regional Office
Mr. Tim Peary, Geologist
4010 W. Broad Street
Richmond, VA 23230

Valley Regional Office
Mr. Rick Criqui, Engineer
116 North Main Street
Bridgewater, VA 22812

ORIGINAL
(Red)

References

- Daniels, P. A. 1974. Geology of the Studley Yellow Tavern, Richmond and Seven Pines Quadrangles, Virginia. Virginia Division of Minerals Resources. Publication 38. Charlottesville, VA.
- Gathwright, T. M. 1978. Geology of the Grottoes Quadrangle, Virginia. Virginia Division of Minerals Resources. Publication 10. Charlottesville, VA.
- Hulcher and Associates. 1982. Operational and Closure Plan for Solid Waste Disposal for Reynolds Metals Company Bellwood Reclamation Plant. Richmond, VA.
- National Climatic Center. Climate of Virginia. 1982. Asheville, NC.
- U. S. Department of Agriculture. Soil Survey of Augusta County, Virginia. 1979.
- U. S. Department of Agriculture. Soil Survey of Chesterfield County, Virginia. 1978.
- U. S. Department of Agriculture. Soil Survey of Henrico County, Virginia. 1975.
- U. S. Department of Commerce. Number of Inhabitants in Virginia. 1980. Census of Population, Washington, DC.
- USEPA. 1981. Potential Hazardous Waste Site, Preliminary Assessment. Washington, DC.

P.O. Box 25249
Richmond, VA 23260

ANALYTICS NO. S0050415
DATE December 9, 1981

Mr. C. R. Bent
Reynolds Metals Company
1 W. Broad Street
Richmond, VA 23261


ORIGINAL

SAMPLE TYPE: 3 Sludge Samples

DATE RECEIVED: 10-26-81

REMARKS: All results are on a wet weight basis.
mcg/g = micrograms per gram


	<u>Sample 1</u>	<u>Sample 2</u>	<u>Sample 3</u>
Loss on Ignition, %	45.7	54.0	32.7
Total Organic Carbon, mcg/g	105,000	198,000	100,000
Solids, %	35.25	27.7	52.05
Aluminum, mcg/g	232,000	143,000	304,000


Harold K. Gibson

Mr. G. W. Smith
Reynolds Metals Company
Bellwood Reclamation Plant
1901 Reymet Road
Richmond, VA 23237

CAST HOUSE DEPARTMENT FLOW CHART

ORIGINAL
(Red)



Photographs

ORIGINAL
(Red)

<u>Photo No.</u>	<u>Title</u>
1-2	Reynolds Metals Company North Plant
1-3	Reynolds Metals Company North Plant
2-2	Reynolds Metals Company South Plant
3-3	Reynolds Metals Company Bellwood Printing Plant
3-4	Reynolds Landfill Located to Rear of Reclamation Plant
3-5	Leachate Eminating from Landfill
4-3	Reynolds Metals Company Grottoes Plastic Plant
5-1	Reynolds Metals Company Southern Gravure Plant

The above listed photographs represent the actual conditions at the Reynolds Metals Company plants. The photographs were taken on January 5, 1984, with the exception of the Grottoes Plant photograph which was taken on January 6, 1984.